


Template for JDM sidemarkers

1. Cut on dashed lines.
2. Cut *outside* bold line of sidemarker hole.
3. Align template with fender landmarks.
4. Remove template and place a piece of 3" masking tape at the location of the hole.
(This will protect of the paint around the hole when it is cut.)
5. Realign template.
6. Confirm the hole is level using a bubble-level against the level gauge.
7. Trace hole onto masking tape.
8. Step back and verify the position and levelness.
9. Cut the hole.



Template for JDM sidemarkers

1. Cut on dashed lines.
2. Cut *outside* bold line of sidemarker hole.
3. Align template with fender landmarks.
4. Remove template and place a piece of 3" masking tape at the location of the hole.
(This will protect of the paint around the hole when it is cut.)
5. Realign template.
6. Confirm the hole is level using a bubble-level against the level gauge.
7. Trace hole onto masking tape.
8. Step back and verify the position and levelness.
9. Cut the hole.